

Leggett & Platt[®]


INCORPORATED
HOSPITALITY PRODUCTS

6755 W. 65th Street—Bedford Park, IL 60638

Parts List For Bed Base

BASE CARTON

- (1) SIDE PANELS—2
- (2) END PANELS—2
- (3) CROSS SUPPORT RAILS—3
- (4) CORNER PLATES—4
- (5) CORNER CLAMPS—4







HARDWARE BAG #404501

- (6) GLIDES—6
- (7) CORNER GLIDES—4
- (8) 6MM X 45MM BOLT—4
- (9) 6MM WING NUT—4

SAVE ALL PACKAGING MATERIALS UNTIL PRODUCT IS FULLY ASSEMBLED. HARDWARE AND SMALL PIECES MAY NOT BE SEEN AND COULD BE ACCIDENTALLY DISCARDED WITH PACKAGING MATERIALS.

PRODUCT FULLY ASSEMBLED



Instruction Sheet

Step 1- Assembly of Side panel and end panel.

- Carefully insert plastic glide (6) and corner glide into pilot holes on side rail (1). SEE FIGURE 1
- Place end panel (2) over corner glide (7). SEE FIGURE 2
- Repeat same steps with the other side rail (1) and end panel (2).

FIGURE 1





FIGURE 2





Step 2- Assembly of Corner Plates and Corner Clamps.

- Place corner plate (4) over pilot holes on side panel (1) and end panel (2). SEE FIGURE 3
- Insert bolt (8) into corner plate (4).
- Place corner clamp (5) under and between side panel (1) and end panel (2) rail. SEE FIGURE 3
- Secure corner plate (5) and corner clamp (5) with wing nut (9).

DO NOT TIGHT WING NUT COMPLETELY

FIGURE 3



Step 3- Assembly of Cross Support Rails.

- Carefully insert legs on cross support rails (3) into slot holes on side rails (1). SEE FIGURE 4
- Align legs on cross support rails (3) over glides (6) on both side rails and then press down on cross support rail (3) leg until fully inserted.
- Tighten wing nut (9) completely. STEP 2 FIGURE 3

FIGURE 4

